


1—Stripping Cable

- **Mark cable at desired strip length and solder sleeve**



- * **Using a razor blade score and crack jacket for strip length**



- **Score jacket lengthwise**



- * **Remove jacket**



- **Push shield back to bunch it up**



- * **Use a small scissors to cut shield lengthwise**




- **Cut shield off completely**




- * **Shield removed**




- **Push back binder tape**



- * **Cut binder tape lengthwise with a small scissors**





- **Cut off binder tape**



- * **Cut off fillers**




- Score/crack jacket for solder sleeve * DO NOT REMOVE jacket (LATER)



- Remove outer insulators
Use a 20 awg stripper


* BE CAREFUL NOT TO NICK WIRES



- Slide on your solder sleeve
- Strip inner insulators, use a 24 awg stripper



- Remove jacket for the solder sleeve



- * Ready to heat your solder sleeve over shield

