Digital Touch Tachometer

Page 1 of 2



This Digital Touch Tachometer provides accurate measurement of spindle speeds in RPM and surface speed in m/min

Clear LCD Display
5 x 10mm high digits

Sampling time: 1 sec. (over 15 rpm)

Memory: Last value, Max value, Min value

Time Base: Quartz crystal

Circuit: Single chip microprocessor, LSI chip

Power: 4 x 1.5v AA batteries

Power consumption: Approx. 80mA during operation


Operating Temperature: 0 - 50°C

Size: 190 x 72 x 37mm

Weight: 280g (including batteries)

Packed Weight and Dimensions

Code	Description	Weight g	W mm	H mm	L mm
59-800-838	Digital Touch Tachometer	746	135	80	255



- 1 Adaptor Holder
- 2 Rotating Spindle
- 3 Display Panel
- 4 Measure Button
- 5 Function Switch
- 6 Memory Button
- 7 Battery Cover
- A Rubber Cone (internal fitting)
- B Rubber Wheel (external fitting)
- C Surface Speed Wheel

Method	Range	Resolution	Accuracy
Rotation / rpm	2.5 - 19,999 rpm	0.1 rpm for 0.5 – 999.9 rpm	$\pm (0.05\% + 1 \text{rpm})$
		1 rpm over 1000 rpm	
Surface / m/min	0.05 – 1,999.9 m/min	0.01 m/min for 0.05 – 99.99 m/min 0.1 m/min over 100 m/min	$\pm (0.05\% + 0.03 \text{m/min})$

Copyright: Linear Tools 2010

Digital Touch Tachometer

Page 2 of 2

Measuring Procedures

RPM Measurement:

Select correct Rubber Cone required for either spindle or hole location and fit to the Adaptor Holder Slide Function Switch to RPM position

Lightly press Rubber Cone into the centre hole of the rotating spindle or the Rubber Wheel onto the revolving shaft

Ensure that the centre lines of the Tachometer and the revolving shaft are correctly aligned and turn synchronously together


Depress Measure Button until the reading stabilises (approximately 2 seconds)

The RPM value will now be displayed

Surface Speed Measurement

Fit Surface Speed Wheel to the Adaptor Holder
Slide Function Switch to M/MIN position
Apply Surface Speed Wheel to moving surface ensuring they both move synchronously
Depress Measure Button until the reading stabilises (approximately 2 seconds)
The M/MIN value will now be displayed

Memory



Following release of the Measure Button Max, Min and Last Value can be recalled in turn by depressing the Memory Button

Max value symbol: "UP"
Min value symbol: "dn"
Last value symbol: "LA"

Battery Replacement

When the battery voltage falls below 5v, a small battery image will appear on the display screento indicate that the battery requires changing

Slide the battery cover away from the instrument and remove the old batteries

Replace with 4 new 1.5v AA batteries ensuring that they are correctly aligned as marked inside the case

Batteries should be removed if the instrument is not to be used for an extended time Used batteries should be disposed of in the correct way

Copyright: Linear Tools 2010