




	<p>Accuracy conforms to DIN 863 Resolution: Metric 0.01mm, Models above 25mm supplied with setting rod Micro fine graduations for accurate reading Tungsten carbide measuring faces Spindle locking lever Ratchet stop Non-glare satin chrome barrel and sleeve Blue baked enamel hammer tone finish Supplied in fitted case with adjustment tools</p>
--	---

Packed Weight and Dimensions

Code	Description	Weight g	W mm	H mm	L mm
50-190-025	Thread Micrometer: 0-25mm	531	105	45	192
50-190-050	Thread Micrometer: 25-50mm	681	115	45	223
50-860-200	Thread Element Set Nos. 1 - 6	54	35	22	55

	<table border="1"> <thead> <tr> <th>Code</th> <th>Range mm/</th> <th>C mm</th> <th>L mm</th> <th>Accuracy mm</th> </tr> </thead> <tbody> <tr> <td>50-190-025</td> <td>0-25</td> <td>26</td> <td>42</td> <td>+/- 0.004</td> </tr> <tr> <td>50-190-050</td> <td>25-50</td> <td>38</td> <td>67</td> <td>+/- 0.004</td> </tr> </tbody> </table> <p>1 Floating Anvil lock 2 Floating Anvil 3 Spindle 4 ratchet</p>	Code	Range mm/	C mm	L mm	Accuracy mm	50-190-025	0-25	26	42	+/- 0.004	50-190-050	25-50	38	67	+/- 0.004
Code	Range mm/	C mm	L mm	Accuracy mm												
50-190-025	0-25	26	42	+/- 0.004												
50-190-050	25-50	38	67	+/- 0.004												


	<p>Thread Elements:</p> <table border="1"> <thead> <tr> <th>Element No.</th> <th>Pitch Range</th> <th>TPI Range</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0.4 - 0.5</td> <td>64 - 48</td> </tr> <tr> <td>2</td> <td>0.6 - 0.9</td> <td>44 - 28</td> </tr> <tr> <td>3</td> <td>1.0 - 1.75</td> <td>24 - 14</td> </tr> <tr> <td>4</td> <td>2.0 - 3.0</td> <td>13 - 9</td> </tr> <tr> <td>5</td> <td>3.5 - 5.0</td> <td>8 - 5</td> </tr> <tr> <td>6</td> <td>5.5 - 7</td> <td>4.5 - 3.5</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>Elements in Set</th> <th>Supplied with</th> <th>Range</th> </tr> </thead> <tbody> <tr> <td>1 - 5</td> <td>50-190-025</td> <td>0 - 25mm</td> </tr> <tr> <td>2 - 6</td> <td>50-190-050</td> <td>25 - 50mm</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>Code</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>50-190-200</td> <td>Set of 6 pairs of Elements No 1 - 6</td> </tr> </tbody> </table>	Element No.	Pitch Range	TPI Range	1	0.4 - 0.5	64 - 48	2	0.6 - 0.9	44 - 28	3	1.0 - 1.75	24 - 14	4	2.0 - 3.0	13 - 9	5	3.5 - 5.0	8 - 5	6	5.5 - 7	4.5 - 3.5	Elements in Set	Supplied with	Range	1 - 5	50-190-025	0 - 25mm	2 - 6	50-190-050	25 - 50mm	Code	Description	50-190-200	Set of 6 pairs of Elements No 1 - 6
Element No.	Pitch Range	TPI Range																																	
1	0.4 - 0.5	64 - 48																																	
2	0.6 - 0.9	44 - 28																																	
3	1.0 - 1.75	24 - 14																																	
4	2.0 - 3.0	13 - 9																																	
5	3.5 - 5.0	8 - 5																																	
6	5.5 - 7	4.5 - 3.5																																	
Elements in Set	Supplied with	Range																																	
1 - 5	50-190-025	0 - 25mm																																	
2 - 6	50-190-050	25 - 50mm																																	
Code	Description																																		
50-190-200	Set of 6 pairs of Elements No 1 - 6																																		

	<p>Setting Master</p> <table border="1"> <thead> <tr> <th>Supplied with</th> <th>L</th> <th>Angle</th> <th>d</th> <th>Accuracy</th> </tr> </thead> <tbody> <tr> <td>50-190-050</td> <td>25mm</td> <td>60 deg.</td> <td>7mm</td> <td>0.003mm</td> </tr> </tbody> </table>	Supplied with	L	Angle	d	Accuracy	50-190-050	25mm	60 deg.	7mm	0.003mm
Supplied with	L	Angle	d	Accuracy							
50-190-050	25mm	60 deg.	7mm	0.003mm							

Mechanical Thread Micrometers

Page: 2 of 4

Initial Setup



Select, clean and insert the required pair of thread elements

Check the elements are free to rotate to ensure they align with the thread helix when taking measurements

Unlock the adjustable fixed anvil to allow it to float when setting the spindle

For the 0-25mm model set the micrometer spindle to read zero

Push the adjustable fixed anvil to nest the single point element inside the V angle element and lock in this position

Wind back the spindle from the zero position then re-advance the spindle towards the fixed element. Use the ratchet stop to finally nest the 2 elements together. Rotate the ratchet stop 1 ½ to 2 revolutions to exert a constant measuring force

When fully closed the zero position on the thimble should coincide with the horizontal line on the sleeve

If the two lines do not coincide, small adjustments can be made by using the “C” spanner provided

Insert the “C” spanner into the hole at the back of the sleeve and gently turn the sleeve in the direction required to achieve line up

The micrometer is now set and ready for use

For the 25mm model set the micrometer spindle to read 25mm

Push the adjustable fixed anvil so that the thread elements nest positively into the setting master and lock in this position

Wind back the spindle from the zero position then re-advance the spindle towards the setting master. Use the ratchet stop to finally nest the elements into the setting master. Rotate the ratchet stop 1 ½ to 2 revolutions to exert a constant measuring force

When fully closed the zero position on the thimble should coincide with the horizontal line on the sleeve

If the two lines do not coincide, small adjustments can be made by using the “C” spanner provided


Insert the “C” spanner into the hole at the back of the sleeve and gently turn the sleeve in the direction required to achieve line up

The micrometer is now set and ready for use



Clean micrometers and check zero position regularly during use to ensure their continued accuracy

After use always clean and replace the micrometer in its box



Mechanical Micrometers



Reading Examples: Metric

 <p>Example for division 0.01mm Reading: From Sleeve: 6mm From thimble: 0.11mm Final readings should be $6. + 0.11 = 6.11\text{mm}$</p>	 <p>Example for division 0.002mm Reading: From Sleeve: 4mm From thimble: 0.23mm From vernier of sleeve: 0.004mm Final readings should be $4 + 0.23 + 0.004 = 4.234\text{mm}$</p>
---	---

Reading Examples: Inch

 <p>Example for division .001" Reading: From sleeve: $.2 + .025 = .225"$ From thimble: .0150" Final readings should be: $.2000" + .0250" + .0150" = .2400"$</p>	 <p>Example for division 0.0001" Reading: From Sleeve: $.2 + .025 = .225"$ From thimble: .0050" From vernier of sleeve: .0004" Final readings should be $.2000" + .0250" + .0050" + .0004" = .2304"$</p>
---	---

Mechanical Micrometers

Page: 4 of 4

Cleaning and Basic Checking Procedure

Remove any oil, grease, dust or small particles which may cause damage to the micrometer or affect its accuracy when taking measurements. Use a soft lint free cloth or paper together with a proprietary instrument cleaning agent. Do not use acetone as this can damage parts of the micrometer

Before use check that the ratchet mechanism functions correctly

Check the spindle movement by using the ratchet stop to traverse the spindle through its complete travel

Check that the measuring faces are in good condition

Check the locking mechanism works correctly

Zero Point Checking and Adjustment

Use the ratchet stop to move the spindle until it touches the fixed anvil. Allow the ratchet to turn $1\frac{1}{2}$ to 2 revolutions for the final positioning

The zero point on the thimble should now coincide with the reference graduated base line on the sleeve

For micrometers above 25mm / 1" use the supplied setting standard or a gauge block to check the zero position

If the zero point does not line up as required, it can be corrected by using the following procedure

When the zero point deviation on the thimble is under 2 divisions from the graduated base line

Turn the sleeve using the "C" spanner provided until correct alignment is achieved

When the zero point deviation on the thimble is over 2 divisions from the graduated base line

Hold the frame and the thimble and loosen the ratchet stop using the spanner provided

Disconnect the coupling of the thimble to the spindle by giving a light shock to the side of the thimble

Turn the thimble until the zero point is in alignment with the base line on the sleeve

Press the thimble against the spindle and re-tighten with the spanner to achieve a positive coupling

Re-check the zero position, any final small adjustment can now be made using the "C" spanner to re-position the sleeve to the thimble zero

Reading the Micrometer

When reading the micrometer ensure that your line of sight is directly above the graduated scale on the sleeve and the thimble scale to avoid parallax reading errors

Ensure that the micrometer and the work piece are at the same temperature

Handle the instrument with care, if it is dropped or knocked in any way it must be rechecked for correct working and accuracy as above