Electronic Micrometer 50-715-025

Page 1 of 3



DIN 863/1

IP-40

Clear LCD Display

Metric/Inch Conversion

Relative & Absolute Modes

Resolution 0.001mm/0.00005"

Tungsten Carbide Anvils

Auto Power Off after 5 minutes

Friction Thimble

Spindle Lock Lever

Plastic Heat Guard


Painted Frame

Supplied with Ball Anvil Attachment

Supplied in fitted case

Packed Weight and Dimensions


Code	Description	Weight g	W mm	H mm	L mm
50-715-025	Electronic Micrometer 0-25mm / 0 -1"	444	105	45	192




Code	Range	С	L	В	D	Accy
	mm/1nch	mm	mm	mm	mm	mm
50-715-025	0-25/0-1"	27.5	32	6	3	0.002


Repeatability: 0.001 mmMeasuring force: 5-10 NOperating temperature; 0.001 mm 0.001 mm0.001 mm

Power: 1 x SR44: 1.5V battery



- 1 Frame
- 2 Anvil
- 3 Spindle
- 4 Locking Device
- 5 Ratchet Friction Thimble
- 6 Quick Drive
- 7 Spanner
- 8 Frame Cover
- 9 ON/OFF / SET Button
- 10 LCD Display
- 11 ABS/INC / Unit Button
- 12 Battery Cover





Accessories supplied:

A: Ball Anvil will fit on either the anvil or spindle as required


B: Tool for removing and replacing the battery cover

Copyright: Linear Tools 2010

Electronic Micrometer 50-715-025

Page 2 of 3

Display options



汝 Battery low voltage indicator ABS Absolute measuring mode Relative measuring mode INC Origin set Set

Inch or metric display in

Setting and Use Instructions

Clean micrometer spindle and measuring anvils with soft cloth or paper to remove any oil or particles which may affect the measurements

Ensure that the micrometer is thermally stabilised with the temperature where it is to be used Ensure that the spindle lock is off

Absolute Measurement

Press and release the ON/OFF / SET button to power up the micrometer. (ABS will show on the display) Choose either inch or metric measuring system by pressing the ABS/INC / UNIT button for 2 seconds (mm or in will show on the display)

Advance the spindle towards the fixed anvil. Use the friction thimble to finally close the 2 anvils together. Rotate the thimble 1 ½ to 2 revolutions to exert a constant measuring force

To zero the micrometer in this position press and hold the ON/OFF / SET button for 2 seconds The micrometer is now ready to use in Absolute mode

Relative Measurement

Press and release the ON/OFF / SET button to power up the micrometer. (ABS will show on the display) Seat the micrometer anvil and spindle across the desired setting piece using the friction thimble Press and release the ASBS/INC / UNIT button (INC will show on the display) and the display will show zero The micrometer is now ready to take measurements and will indicate either + or - variations from the original setting piece size

Operating Care

Clean measuring faces with a clean soft cloth only

Do not use any organic solvent for cleaning such as acetone etc.

Keep instrument away from strong magnetic fields and high voltage environments which can affect the correct working of the electronic pack

Prevent the ingress of oil and liquids into the electronics

Do not use or store the micrometer in direct sunlight, or in an excessively hot or cold environment The Instrument can be turned on by either using the ON/OFF button or simply by turning the thimble To conserve the battery the instrument should be turned off using the ON/OFF button or it will turn off automatically after 5 minutes of non use

Remove battery if the instrument is not to be used for a long period of time

Do not disassemble or drop the instrument

Do not mark the instrument by engraving, etching or any other permanent method of marking as this will invalidate the warranty

Copyright: Linear Tools 2010

Date: 18-11-2010

Electronic Micrometer 50-715-025

Page 3 of 3

Specifications:

Measuring Force: 5 - 10N

Power Consumption: Greater than 35 milliamps

Operating Temperature: 0-40 deg.CStorage Temperature: -20 to 60 deg. C

Protection Class: IP54 (resistant to water splash)

Fault Finding

Failure	Causes	Remedy
Display: "E 1"	Measured value is over display	Reset the origin or change to
	range	relative mode
Display: "E 3"	1 The micrometer is disturbed	1 Reset the battery
	2 Something wrong with sensor	2 return the micrometer for repair
Measured value is not correct	1 Measuring surfaces are not clean	1 Clean measuring surfaces
	2 The origin is incorrect	2 Reset the origin
Display is confused or dead	Strong disturbance to micrometer	Reset battery
No display	Battery voltage below 1.45V	Replace battery
Display is blurring		
Battery sign appears		

Copyright: Linear Tools 2010